



70ft, Dave Thomas, 1999, Traditional Style

**BERTHS:**

4

**TOILET:**Mansfield pump
out & Porta potti**HEATING:**Bastro Thermo Top
Diesel Boiler**SURVEY:**

-

**B.S.C:**

Aug 2019

**BLACKING:**

Aug 2014

**ENGINE:**

Barrus 220

**LAYOUT:**

Standard

**Whilton
marina**Whilton Locks, Near Daventry,
Northants, NN11 2NH

01327 842577

sales@whiltonmarina.co.uk

www.whiltonmarina.co.uk

**For further information please see
a member of the sales team.**

It is the responsibility of the buyer to ensure that all particulars given in the course of the purchase of the boat are accurate. Such particulars are intended only as a guide and do not constitute a term of any contract.



Boat Specification

Plating Specification
Flat, V-Hull or Keeled
Fitted out By
Fixed Berths
Additional Berths

10/6/5/4mm
Flat Hull
Merlin Narrowboats
Fixed double bed & Single
Double sofa bed

Engine Specification

Engine Make
No. Of Cylinders
Keel, Water or Air Cooled
Gearbox Make
Aqua Drive
Bow Thruster
Diesel Tank Capacity

Barrus 220
4
Raw Water Cooled
PRM 260 Hydraulic
-
Yes
35 Gallons

Hot Water & Heating Systems

Source of Hot Water
Central Heating
Solid Fuel Stove
Water Tank Capacity
Material used
Additional Systems

Lagged Calorifier
Bastro Thermo Top Diesel Boiler
Clearview 5kw
120 gallons
Polyproplene
Automatic Water Pump

Electrical System & Components

12 Volt Lighting
240 Volt Landline
Inverter
Generator
Batteries
Additional Systems

Yes
Yes
Spark 3kw
HFL
2 x bow thruster, 1 starter & 3 domestic batteries
3 x Solar panel

Bathroom Specification

Type Of Toilet
Bath Fitted
Separate Shower Fitted
Vanity Basin Fitted
Additional Systems

Mansfield pump out & Porta potti
-
Yes
Yes
-

Kitchen Specification

Make & Model Of Cooker
Separate Hob
Microwave Fitted
Make & Model Of Fridge
Gas, 12 volt or 240 volt
Additional Systems

Indesit cooker
-
-
Beko fridge & Beko freezer
240v
-

Fit Out Materials

Insulation Used

Types Of Wood Used

Window Types

Materials Used

Bulls Eye, Pigeon Box or Houdini Hatch

Exterior Doors

Side Hatches

Front & Back Covers

Sprayfoam

-

Hopper & port holes

Aluminium

-

-

Yes x1

Cratch & cover

History Of Vessel

Boat Safety Certificate

Last Hull Blacking

Anodes

Further Maintenance

Recent Survey

Additional Information

Aug 2019


Aug 2014

4 fitted Aug 2014

Engine Serviced Jan 2018

-

-





Whilton Locks, Near Daventry,
Northants, NN11 2NH
01327 842577
sales@whiltonmarina.co.uk
www.whiltonmarina.co.uk

**For further information please see
a member of the sales team.**

It is the responsibility of the buyer to ensure that all particulars given in the course of the purchase of the boat are accurate. Such particulars are intended only as a guide and do not constitute a term of any contract.

